

17-12 Chapel Street, Bradford, Grade 2 listed
Selected Photos
Architectural Services Tender
June 2025



17-21 Chapel Street - East Facade, Chapel Street Elevation, January 2025. Double cast iron railed gates in the centre and a radial cast iron fanlight above. The majority of Ashlar stonework is in reasonable condition. See next photo for an example of work required though. The stonework areas behind the failed cast-iron rainwater goods need cleaning but are otherwise mostly sound.



17-21 Chapel Street, East Elevation - Fan light and delaminating Ashlar Stone cill, window on floor above



17-21 Chapel Street - Main Roof, (east) Chapel Street Elevation showing the lead-lined gutter, three courses of Westmorland Stone slates to eaves with traditionally laid diminishing courses of Welsh slate above.



17-21 Chapel Street - Timber Decay in window, Chapel Street (East) Elevation



Water Ingress at Eaves - most likely caused by failure of the lead lined gutters directly above.